

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/02/2015
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155596	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02, 03 B. WING _____		(X3) DATE SURVEY COMPLETED R 08/28/2015
NAME OF PROVIDER OR SUPPLIER LAKELAND SKILLED NURSING AND REHABILITATION			STREET ADDRESS, CITY, STATE, ZIP CODE 500 N WILLIAMS ST ANGOLA, IN 46703		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>INITIAL COMMENTS</p> <p>A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 06/30/15 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 08/28/15</p> <p>Facility Number: 000474 Provider Number: 155596 AIM Number: 100290510</p> <p>At this PSR survey, Lakeland Skilled Nursing and Rehabilitation was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The original building consisting of the 200, 300 halls and the service hall was surveyed with Chapter 19, Existing Health Care Occupancies.</p> <p>This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and areas open to the corridors. The resident rooms on the 300 hall and 400 hall had hard wired smoke detectors. The resident rooms on the 200 hall had battery operated smoke detectors. The facility has a capacity of 75 and had a census of 69 at the time of this survey.</p> <p>All areas where the residents have customary access were sprinklered. The facility had a detached shed providing facility services including</p>	{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/02/2015
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155596	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02, 03 B. WING _____		(X3) DATE SURVEY COMPLETED R 08/28/2015
NAME OF PROVIDER OR SUPPLIER LAKELAND SKILLED NURSING AND REHABILITATION			STREET ADDRESS, CITY, STATE, ZIP CODE 500 N WILLIAMS ST ANGOLA, IN 46703		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 1	{K 000}			
{K 000}	INITIAL COMMENTS A Post Survey Revisit (PSR) to the Life Safety Code Recertification and State Licensure Survey conducted on 06/30/15 was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a). Survey Date: 08/28/15 Facility Number: 000474 Provider Number: 155596 AIM Number: 100290510 At this PSR survey, Lakeland Skilled Nursing and Rehabilitation was found in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC) and 410 IAC 16.2. The new 2012 addition of the 400 hall was surveyed with Chapter 18, New Health Care Occupancies. This one story facility was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and areas open to the corridors. The resident rooms on the 300 hall and 400 hall had hard wired smoke detectors. The resident rooms on the 200 hall had battery operated smoke detectors. The facility has a capacity of 75 and had a census of 69 at the time of this survey. All areas where the residents have customary access were sprinklered. The facility had a	{K 000}			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/02/2015
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155596	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02, 03 B. WING _____		(X3) DATE SURVEY COMPLETED R 08/28/2015
NAME OF PROVIDER OR SUPPLIER LAKELAND SKILLED NURSING AND REHABILITATION			STREET ADDRESS, CITY, STATE, ZIP CODE 500 N WILLIAMS ST ANGOLA, IN 46703		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	Continued From page 2 detached shed providing facility services including maintenance supplies that was not sprinklered.	{K 000}			